

Landing Light Assembly:

Grimes Landing Light Assembly (Overhauled):

Part Number	Core Charge	Notes
45-0128-3	1,000.00	
45-0148-*	1,000.00	
45-0148-9	3,000.00	Additional cost to overhaul & convert from the -1 thru -8
45-0148-10	3,000.00	Additional cost to overhaul & convert from the -1 thru -8
45-0182-*	1,000.00	
45-0213-1		Replaced With 45-0350-*
45-0241-*	1,000.00	
41850A-*	1,000.00	
D-3040-*	500.00	
G-2905-24	500.00	Motor for G3600 series
G-3001A	500.00	Additional Cost if Gears Are Bad Cessna #0870132-1; Additional Cost
G-3600A-1	1,000.00	if Gears Are Bad
G-3600A-5	1,000.00	Additional Cost if Gears Are Bad
G-3801-1A	500.00	
G-4710A-3	500.00	
G-5400-6	500.00	
G-6250-*	1,000.00	
G-8385-*	850.00	
46-0954-1	500.00	Gearbox for 45-0148-*

* Various Dash Numbers Are Available.

Cessna Reduction Units (Overhauled):

Part Number	Core Charge	Notes
0894000-8	1,600.00	S/A 0894000-2
0894000-10	1,600.00	S/A 0894000-11
5115237-10	1,600.00	Must update to -16
5115237-16	2,500.00	Must update with new gears
5565175-31	2,500.00	Must update to -38
5565175-38	2,500.00	
5565175-41	2,500.00	
9882015-1 & -2	1,800.00	Repair Only
9882000-1 & -2	1,800.00	Repair Only

Rotating Beacons:

Grimes Rotating Beacons (Overhauled):

Part Number	Core Charge	Notes
40-0100-*	750.00	Teardrop; Motor Extra
40-0103-*	250.00	Round type: (-31) 50-364261-15 Motor Extra