

**REPLACEMENT AIRCRAFT PARTS CO.**

445 Cardinal Lane Hartland, WI 53029, USA

Phone: (262)367-2292

Fax: (262) 367-7158

www.rapcoinc.com

Rapco Replacement Brake Disc and Linings for Cessna Aircraft with McCauley Brakes**Disc Application**

Cessna Aircraft Model	# Bolt Holes	Depth	Wheel Assembly	Brake Assy.	McCauley Brake Disc	Rapco Brake Disc
150, 150A	6	2.0"	C613004-0104 C613003-0101	C-30018-4 C-30018	B-30440	RA164-30440
	6	2.1"	or C163001-0102 C163002-0101	C-30018-4	B-30195 B-30007	RA164-30195
152, A152, F152, FA152	3	1.5"	C163005-0101 or C163006-0101	C-30018-5 C-30764-5	C30615-1	RA164-30615-1
172, F172, R172, FR172	6	2.0"	C163004-1004 C163003-0101	C-30018-4 C-30018	B-30440	RA164-30440
	6	2.1"	or C163003-0102 or C163004-0104 C163002-0101	C-30018-4 C-30018-4	B-30195 B-30007	RA164-30195
172, F172, 172RG	3	1.5"	C163006-0101	C-30764-5	C30615-1	RA164-30615-1
177 177RG	3	1.5"	C163005-0101 C163005-0101	C-30764-5 C-30018-5	C30615-1	RA164-30615-1
	3	1.5"	or C163006-0101	C-30764-5	C30615-1	RA164-30615-1
180, 185	6	2.2"	C163004-0103	C-30018-5,-6	C30414	RA164-30414
	6	2.3"	C163004-0101	D-30118-5,-6	C30888	RA164-30388
	3	1.7"	C163006-0103 Std.	C-30118-3,-4	C30615-3	RA164-30615-3
	3	1.9"	C163006-0102 HD	D-30118-5,-6	C30615-2	RA164-30615-2
182, F182	3	1.5"	C163006-0101 or C163006-0103	C-30764-5 C-30764-5	C30615-1	RA164-30615-1
	3	1.7"	C163006-0103	C-30118-3,-4	C30615-3	RA164-30615-3
R182, FR182, TR182	6	2.1"	C163004-0102	D-30118-3,-4	C30398	RA164-30398
	6	2.3"	C163004-0101	D-30118-5,-6	C30388	RA164-30388
	3	1.7"	C163006-0103 Std.	D-30118-3,-4	C30615-3	RA164-30615-3
	3	1.9"	C163006-0102 HD	D-30118-5,-6	C30615-2	RA164-30615-2
210, T210, P210	6	2.1"	C163006-0103	D-30118-3,-4	C30398	RA164-30398
	3	1.7"	C163006-0103	C-30118-3,-4	C30615-3	RA164-30615-3

Lining Application

Cessna - McCauley Brake Assembly	McCauley Lining	Rapco Lining
All assemblies listed above.	B-30026	RA66 -109

Rivets

Original McCauley brake assemblies use the RA66-109 linings with RA105-007 rivets, .228 in length. Back plates and pressure plates that were later produced by Cleveland as after market replacements for those brake assemblies, require the longer RA105-002 rivets, .280 in length.