

BRACKETT AERO FILTERS, INC.



INSTRUCTIONS

ASSEMBLY PART NO. BA-4510

APPROVED ON AIRCRAFT MODELS: Piper PA24-260C, SN 24-4783 SN 24-4804 & up.

REPLACES: Piper PN 26874-00

FAA APPROVAL DATA: STC-SA71GI List No. 1 FAA-PMA Supplement List No. 1

Your new polyurethane air filter element has been designed to provide maximum dust collecting efficiency, non-restrictive air flow, and economical element replacement, while maintaining a lightweight filter. The element has been treated with a distinctive treatment called a wetted agent and is approximately 98% efficient. The wetted agent is an accompaniment in the efficient capturing of dust. In addition, the element has received a fire retardant treatment. For the above reasons, replace the element each 200 hours of use, 12 months or when 50% covered with foreign material. DO NOT WASH AND REUSE.

INSTALLATION INSTRUCTIONS

- Step 1. Remove original air filter and discard.
- Step 2. Remove element BA-4505 from plastic bag and install into frame assembly. Install grill with hardware kit. NOTE: Element "ENGINE SIDE" placement toward screen.
- Step 3. Install filter assembly onto aircraft using the same procedure as original with the original clips, check that gasket is fully seated.
- Step 4. NOTE: After initial installation of filter assembly, fill out FAA Form 337 for return to service. On future replacement of parts this form will not be required.
- SERVICING: Under normal conditions, replace filter element, PN BA-4505, after 200 hours use or 1 year intervals. Under severely dusty conditions, <u>check</u> <u>daily</u> and replace when element is 50% covered with foreign material. For Continued Airworthiness Instructions, see Form I-194.

United States Of America Bepartment of Transportation - Federal Abiation Administration



Number SATIGL

This Certificate issued to

BRACKETT AERO FILTERS, INC. 7052 Government Way Kingman, Arizona 86401

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations.

 Original Deduct Type Certificate Number : * *See attached Approved Model List (AML)

 Make :
 *(AML) No. SA71GL for list of approved aircraft

 Model :
 *models and applicable airworthiness regulations.

Description of Type Design Change: Installation of air filters in accordance with AML No. SA71GL dated April 17, 1995, or later FAA approved revision.

Bimitations and Conditions. Approval of this change in type design applies to the above aircraft model(s) only. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and FAA Approved Model List (AML) No. SA71GL dated April 17, 1995, or later FAA approved revision must be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application. January 9, 1975

Date of issuance February 21, 1975



Date reissued March 3, 1983, June 20, 2000

Date amended . April 17, 1995

By direction of the Administrator

Hm Liza Mal

Manager, Tech. and Admin. Support Staff Los Angeles Aircraft Certification Office (Tule)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both

This certificate may be transferred in accordance with FAR 21.47.

FAA APPROVED MODEL LIST (AML) NO. SA71GL BRACKETT AERO FILTERS, INC. FOR INSTALLING AIR FILTERS Issue Date: April 17, 1995

AML	AMENDMENT DATE	7/12/95	7/12/95								
	CERT. BASIS	FAR 23	FAR 23		CAR 3	CAR 3		CAR 3			
ORIGINAL TYPE	CERTIFICATE NUMBER	A11EA	A16EA	*** END OF DATA ***	A782		1A15	*** END OF DATA ***	5A4	OF DATA ***	
	AIRCRAFT MODEL	AA-1, AA-1A, AA-1B, AA-1C	AA-5	*** END	Navion B, Navion G, Navion H		PA-24-260 (SN 24-4783, 24-4804 and UP)		50, B50, C50, D50/A/B/C, D50E	END ***	
	AIRCRAFT MAKE	Gulfstream	Gulfstream		Jimmie Thompson		Piper		Beech		
P VING	REVISION & DATE	B 6/14/95			N/C 9/18/93		A 9/18/93			A 6/25/93	
TOP DRAWING	NUMBER		BA-4210			BA-4310		BA-4510		BA-4810	
AIR FILTER	MODEL NUMBER		BA-4210			BA-4310		BA-4510		BA-4810	
	ITEM	30 30			31		32			33	



BRACKETT AIR FILTER DOCUMENT I-194

PLACE IN AIRCRAFT RECORDS

CONTINUED AIRWORTHINESS INSPECTION REQUIREMENTS AS PER FAR 23.1529 AND GENERAL PROCEDURES OF PART 43

INSPECTION INTERVALS: Pre-flight inspections, engine backfire inspection, 100 hour inspections, annual inspections, filter element replacements.

INSPECTION PROCEDURES

- A. Pre-flight inspection: Per Pilots Operating Handbook, check filter assembly for security, damage or 50% contamination of element face. If found report to maintenance personnel prior to flight.
- B. Engine start-up backfire inspection: Prior to flight, check the entire intake system for security or damage. If a fire was present, the downstream face of the foam element will show erosion. If any irregularities are found see Chart I and also refer to the Aircraft Maintenance Manual for the intake system.
- C. At element replacement intervals: With the element removed, inspect the filter grill, filter frame, filter mountings and entire intake system for security, wear and any deformation. Note: On filter assemblies with gaskets, visually inspect inside and outside of frame for any signs of gasket looseness, movement or deterioration. If found refer to Chart I or the proper maintenance manual for your aircraft or component.

REDI	INSTRUCTIONS
Х	COMPLETE NEW ASSEMBLY
X	 ON FILTER FRAME, REMOVE OLD NEOPRENE GASKET AND ALL TRACES OF ADHESIVE DOWN TO A CLEAN ANODIZED FRAME SURFACE. USE ADHESIVE 3M#847 OR DOW CORNING RTV-732. COAT ENTIRE MATING SURFACE (GASKET TO FRAME). APPLY ADHESIVE FOLLOWING MANUFACTURER'S LABEL DIRECTIONS. WHEN FRAME AND GASKET ARE PLACED TOGETHER, CLAMP OR WEIGHT DOWN AT .75 LB./SQ. IN. OF CONTACT AREA. ALLOW TO CURE 24 HOURS PRIOR TO INSTALLATION. PRIOR TO REINSTALLATION OF FILTER, CHECK AIRBOX MATING SURFACE FOR IRREGULARITIES. IF FOUND, CORRECT PER MANUFACTURER'S REQUIREMENTS. UPON REINSTALLATION CHECK THAT THE GASKET MAKES 100% CONTACT. THE GASKET SHOULD BE COMPRESSED 50% FOR OPTIMUM SEAL.
Х	REPLACE WITH NEW GRILL
Х	REPLACE UNSERVICEABLE WITH NEW
Х	COMPLETE NEW ASSEMBLY
Х	COMPLETE NEW ASSEMBLY (ASSEMBLIES USING SCREEN GASKETS PRE 1981; BA-4106, BA-5110 AND BA-8110.)
Х	REPLACE ELEMENT
	X X X X X X X X