

Grimes Rotating Beacons (Overhauled) (Cont.):

Part Number	Core Charge	Notes
40-0100-27	750.00	Standard Overhaul, Mtr. Extra
40-0100-27(w/convert)	750.00	Standard overhaul with conversion, Mtr. Extra
40-0117-1	750.00	Motor Extra
40-0127-*	750.00	(-1) 101-360020-3; (-1C) 101-360020-17; (-1) 102-364031-1 (all Teardrop) Mtr. Extra
40-0129-*	300.00	Round type; Mtr. Extra (-7) C621002-0106; (-11) C621002-0107; (-15) C621002-0109; (-17) C621002-0108
40-0168-3	600.00	Motor Extra
D7080A-*	300.00	Round Type; Motor Extra
G-9950-*	750.00	Teardrop; Motor Extra
G-7740A-*	300.00	Round Type; Motor Extra
G8400-*	300.00	Round Type; Motor Extra

Extra Charge For Cracked, Pitted Or Broken Lens: Additional Cost for Motors.

* Various Dash Numbers Are Available.

Rudder/Elevator/Aileron Trim Tab Actuator:

Beech Rudder/Elevator/Aileron Trim Tab Actuator (Overhauled):

Part Number	Core Charge	Notes
50-524161-606 (-604)	1,000.00	Same as 50-524161-10
50-524161-607 (-605)	1,000.00	Same as 50-524161-11
101-524072-1	1,000.00	
101-524079-3	1,000.00	
101-521039-1	1,000.00	
45-524565-3,-5,-11,-13	1,000.00	
96-526000-*	1,000.00	

* Various Dash Numbers Are Available.

Shimmy Dampeners:

Beechcraft Shimmy Dampeners (Overhauled):

Part Number	Core Charge	Notes
114-820052-9	1,000.00	Does not include new piston
35-825145-2	1,000.00	
50-820004-3	1,000.00	
50-820004-3	1,000.00	Price with New Rod Assembly