

BRACKETT AIR FILTERS



The specially treated polyurethane element in the Brackett filter assures near total protection from any foreign material entering the system. Repels water, fire retardant and has good air flow for proper fuel/air ratio. Has no pleats to collect dirt. Low-cost maintenance with increased engine life. FAA approved. Replace original air filter unit with a Brackett assembly. Thereafter, throw away element and replace with new one at minimal cost.

Aircraft Model Assembly	Air Filter P/N	Assy Price	Element P/N	Element Price
Aero Commander: A9, A9A, A9B	BA104	\$33.50	BA3	\$16.50
100-100A	BA8910	\$75.75	BA8905	\$12.50
100-180,112,112A,112B	BA3910	\$73.75	BA3905	\$17.60
112TC,112TC-A,114,114A	BA4010	\$77.75	BA4005	\$18.60
500A-B,560F,680F,FL,FLP,500U	BA151	\$87.75	BA151E	\$22.50
560, 560A, 560E, 680 - L	BA2610L	\$79.90	BA2605L	\$21.50
560, 560A, 560E, 680 - R	BA2610R	\$79.90	BA2605R	\$21.50
Aircoupe: 415C, CD, D, E, G	BA8810	\$51.75	BA8805	\$10.50
F-1, A-1, A2-2	BA4106	\$65.75	BA4108	\$9.50
Beech: 23, A23, A23A, A23-19	BA104	\$33.50	BA3	\$16.50
A23-19A, A-23-24, B23	BA104	\$33.50	BA3	\$16.50
C-23, C24R, A24R, B24R, B19	BA7510	\$76.75	BA7305	\$15.50
33, A33, B33, C33, E33, F33	BA7110	\$77.75	BA7112	\$16.50
C33A,E33A,E33,F33A,F33C,G33	BA7210	\$77.75	BA7112	\$16.50
35, A35, B35 thru S/N2605	BA7310	\$76.75	BA7305	\$15.50
B35,C35,D35,E35,F35,G35,H35,J35	BA7110	\$77.75	BA7112	\$16.50
K35, M35, N35, P35, 35R	BA7110	\$77.75	BA7112	\$16.50
S35 thru S/N D7671	BA7410	\$76.75	BA7112	\$16.50
S35, V35, V35A, V35B,36,A36	BA7210	\$77.75	BA7112	\$16.50
A36TC, B36TC, A45(T-34)	BA7210	\$77.75	BA7112	\$16.50
B45(T-34A), D45(T-34B)	BA7210	\$77.75	BA7112	\$16.50
W/STC SA1450 SW Cont.IO-52O	BA7210	\$77.75	BA7112	\$16.50
E50 (L-23D, RL-23D),F50	BA100	\$111.75	BA7	\$20.95
55, A55, B55	BA7610	\$79.85	BA7605	\$17.65
G50, H50, J50	BA100	\$111.75	BA7	\$20.95
C55, D55, E55, 355	BA6210-1	\$75.75	BA6205	\$15.50
S/N TE768-1078 58 thru S/N TH 740	BA6210-1	\$75.75	BA6205	\$15.50
E55, 355A, SN TE-1079 & up	BA7710	\$77.75	BA7705	\$19.50
58, 58A, SN TH741 & up	BA7710	\$77.75	BA7705	\$19.50
A65, 70, 65-B80, B88	BA100	\$111.75	BA7	\$20.95
76	BA7010	\$81.75	BA7005	\$15.50
77	BA2010	\$67.75	BA6108	\$11.50
95, B95, B95A, D95A	BA7810	\$75.75	BA7805	\$19.55
Bell:				
47G-2, 47G2A, 47G2A-1, 47G-3, 47G-3B	BA102	\$41.50	BA2	\$23.70
47G-3B-1, 47G-3B-2, 47G-3B 2A, 47J, 47J-2	BA102	\$41.50	BA2	\$23.70
47J-2A,47G-3B,47G-3B,47G-3B-1	BA102	\$41.50	BA2	\$23.70
47G-3B-2,47G-4,47G-4A,47G-5,47J-2,47J-2A	BA103	\$63.75	BA9	\$32.90
Bellanca: 14-19-3A, 17-30	BA8110	\$89.95	BA8103-1	\$20.50
17-30A	BA104	\$33.50	BA3	\$16.50
Brantly: B-2, B-2B	BA104	\$33.50	BA3	\$16.50
Cessna: 340,340A,402C,414,414A	BA109	\$69.75	BA22	\$26.55
402B,SN0801 & after,421,T310R	BA108	\$79.95	BA13	\$29.85
421A, 421B, 421C, T310R	BA108	\$79.95	BA13	\$29.85
337, 337A-H, R172K, F337E-336,T41B-D	BA111	\$86.75	BA24	\$20.50
P337, T337 Rear Engine,172RG	BA5810	\$85.75	BA5805	\$16.50
R182, TR182, T-182, FR182	BA2510	\$87.75	BA2505	\$22.50
190, 195, 195A, 195B	BA8410	\$98.80	BA8405	\$32.95
120,140,140A,150,150A-M,152,152A	BA4106	\$65.75	BA4108	\$9.50
170, 170A-M,172, 172A-M	BA5110	\$72.75	BA6108	\$11.50
172N, 172P, F172N, F172P	BA5110A	\$72.75	BA6108	\$11.50
175, 175A-C, L-19	BA101	\$91.75	BA8	\$13.50
177, 177A, B, RG, F177RG	BA5710	\$93.75	BA5705	\$12.50
180 ('53-'55)	BA8010	\$77.75	BA8005	\$14.50
180A-K, 182, 182A-R, F182P, F182Q	BA8110	\$89.95	BA8103-1	\$20.50
185,185A-E,A185E,A185F	BA8110	\$89.95	BA8103-1	\$20.50
188, 188A	N/A	--	BA14	\$25.85
205,205A,210,210A,B,C,310A,B,C,D	BA2110	\$93.75	BA2305	\$20.50
P206A-E, U206A-G, 207, 207A	BA2210L	\$93.75	BA2205-L	\$22.50
210D-N (to SN 64535 w/o air)	BA2210L	\$93.75	BA2205-L	\$22.50
210D-N (to SN 64535 w/o air)	BA2210R	\$100.75	BA2205-R	\$23.50
210N (SN645436 & up w/air), 210R, T210F-N	BA2410	\$99.95	BA2405	\$39.75
P210 All	BA8710	\$102.75	BA8705	\$19.50
310F thru L	BA2310	\$100.75	BA2305	\$20.50
310N-Q, T310P, T310Q, 401 S/N 145-401B S/N 221, 402 S/N 145-402B S/N 800	BA107	\$74.75	BA12	\$26.55
310R	--	--	BA117	\$26.55
F150GthruM,FA150K-L,F152,FA152	BA4106	\$65.75	BA4108	\$9.50
R172K, FR172E-K	BA111	\$86.75	BA24	\$20.50
TP206,TP206A-E,TU206A-G, T207, T207A	BA2410	\$99.95	BA2405	\$39.75
411, 411A	BA-3810	\$83.75	BA3805	\$21.75
Bobcat T-50, AT-17, UC-78, JRC-1	N/A	---	BA2705	\$24.50

EP