

# REPLACEMENT CESSNA PARTS



## CESSNA BEARING ELEVATOR S1003-29A

FAA-PMA Approved.  
Please check your Owner's Manual for Eligibility.  
P/N 06-02538 .....\$2.75

## CESSNA WINDOW LATCH ASSEMBLIES

208 Window Latch Aircraft Assembly .....P/N 06-02522 .....\$628.00  
176 Window Latch Aircraft Assembly .....P/N 06-02523 .....\$656.00



## WASHER FUEL BOWL FOR CESSNA AIRCRAFT

Washer Fuel Bowl for Cessna Aircraft - MC0756015-1.  
P/N 01-01354 .....\$24.85

## CESSNA UNIVERSAL JOINT KIT



A universal joint attaches to each control yoke shaft behind the instrument panel. Replacement of the universal joint is recommended if any free motion or rust around the joint pivots is detected. McFarlane also has FAA-PMA approval for the protection sleeve that slides over the universal joint to reduce vibration wear and act as a safety device. The sleeve is included with every MC0411257 universal joint. Each convenient kit includes nuts and two bolt sizes; only two of the four bolts provided are required when installing the universal joint. ....P/N 05-22942 .....\$359.00

## SEE OUR WEBSITE FOR AIRCRAFT ELIGIBILITY LIST. CESSNA CITATION MAIN GEAR DOOR HINGE PIN

Cessna Citation main gear door hinge pin. Model 550 and 560. PMA.  
P/N 05-12492 .....\$36.50



## CESSNA O-RING NOSE STRUT

MCS1628-329 Cessna O-Ring Nose Strut. FAA-PMA.  
P/N 06-01586 .....\$2.65



## S2418-1 CESSNA SCRAPER RING NOSE STRUT

S2418-1 Cessna Scraper, Ring, Nose Strut. FAA-PMA  
P/N 06-01588 .....\$8.95

## BRASS SHIM TORQUE LINK FAA-PMA APPROVED


Eliminates undampened torque link motion to prevent shimmy.

| Part No. | Cessna Part No. | Thickness | Price ea |
|----------|-----------------|-----------|----------|
| 05-00429 | S1450-6B14-010  | .010"     | \$4.35   |
| 05-00430 | S1450-6B14-007  | .007"     | \$4.50   |
| 05-00431 | S1450-6B14-005  | .005"     | \$4.35   |



## CESSNA BEARING FIN S1004-42A

FAA-PMA Approved. Please check your Owner's Manual for Eligibility. ....P/N 06-02539 .....\$18.85



## CESSNA SPACERS

Spacer sleeve: made of aluminum alloy 2024 overall  
P/N 06-00639 .....\$0.25

## CESSNA STUDS

S115-32 Cessna Stud .....P/N 06-02841 .....\$1.55  
S115-35 Cessna Stud .....P/N 06-02842 .....\$2.45



## 150/152 SEAT RAIL SCREW KIT SR150-SCREW-KIT

This is screw kit specifically for the Cessna 150/152 seat rails. This #10 Structural Screw Kit contains all screws and nuts required to install four seat rails. Kit Contains: 40 MS27039-1-08 Screw 10-32 x .531, 2 MS27039-1-09 Screw 10-32 x .594, 2 MS27039-1-17 Screw 10-32 x 1.094, 40 MS21044N3 Nut, Nylon Lock.....P/N 05-04107 .....\$33.75




## CESSNA MOTOR MOUNT BLOCK LOCK WASHER

One side is embossed with a surface texture for improved locking strength and to make sure the washer does not slip while tightening. FAA approved using stronger material than the original, allowing the standard washer to be eliminated. \*Designed with six tabs instead of two.\*Cessna 180, 182, 185, 188, 205, 206, 207, 210, 310, 320, 411, and 414 model aircraft.....P/N 05-01742 .....\$11.75

## CESSNA FUEL VENT LINES

We now have the improved fuel vent lines approved for many additional Cessna 150, 172, and 175 series aircraft. Parts ending with a "K" suffix indicate the inclusion of a rubber grommet, p/n MS3548-14, and hose, p/n MCS1495-8. **Features:** • Stops environmental and asphalt damage • Fly with known full tanks • Extends useful range • FAA-PMA direct replacement - No STC or 337 for needed



| Model        | Part No. | Price    |
|--------------|----------|----------|
| MC0523559-6  | 05-06982 | \$277.95 |
| MC0523559-6K | 05-06983 | \$283.95 |
| MC0523559-8  | 05-06984 | \$281.95 |
| MS0523559-8K | 05-06985 | \$240.95 |



## CESSNA S1878-1 STUD TRIMOUNT

Cessna S1878-1 Stud Trimount.  
P/N 06-02839 .....\$1.10


## MC1243426-2 UPPER TORQUE LINK ASSEMBLY

A stronger upper torque link for Cessna 210 Aircraft .....P/N 05-22403....\$2,751.00



## CARAVAN SPOILER HINGES

FAA-PMA direct replacement. Eligible for all Cessna Caravan 208,208B. Selective fit components. Cadmium plated stainless pins and anodized aluminum hinges for better corrosion resistance. No looseness in the hinge to start vibration wear.



| Description                        | Part No. | Price    |
|------------------------------------|----------|----------|
| MC2622187-R Hinge, Spoiler, RH TAB | 05-17644 | \$156.75 |
| MC2622187-L Hinge, Spoiler, LH TAB | 05-17648 | \$168.99 |



## CARAVAN TORQUE LINKS

Nose gear torque links for Cessna 208/208B Caravan aircraft. These durable and finely machined replacement torque links are designed to meet the rigors of the Alaskan bush.

| Description       | Part Number | Price      |
|-------------------|-------------|------------|
| Torque Link Upper | 05-12925    | \$991.00   |
| Torque Link Lower | 05-12926    | \$1,043.00 |



## PASSENGER DOOR STEP FOR CESSNA CARAVAN

Engineered for increased longevity and constructed solely from aluminum. No more delamination. Direct replacement for all positions, Cessna P/Ns 2617076-1 (lower), 2617076-10 (upper), and 2617076-11 (middle) ..... P/N 05-22906 .....\$1,658.00

## ROLLER HOUSINGS FOR CESSNA

| McFarlane Part No. | Spruce Part No. | Description               | Price    |
|--------------------|-----------------|---------------------------|----------|
| MC0700645-1        | 05-15011        | Left Seat Roller Housing  | \$250.95 |
| MC0700645-2        | 05-15010        | Right Seat Roller Housing | \$262.95 |
| MC0700645-3        | 05-15009        | Left Seat Roller Housing  | \$262.95 |
| MC0700645-4        | 05-15008        | Right Seat Roller Housing | \$250.95 |
| MC1200603-38       | 05-15012        | Right Seat Roller Housing | \$56.75  |
| MC1200603-38       | 05-15013        | Left Seat Roller Housing  | \$48.80  |
| MC1200603-41       | 05-15015        | Left Seat Roller Housing  | \$225.95 |
| MC1200603-42       | 05-15014        | Right Seat Roller Housing | \$79.75  |
| MC1414104-25       | 05-15001        | Left Seat Roller Housing  | \$192.75 |
| MC1414104-39       | 05-15002        | Left Seat Roller Housing  | \$146.75 |
| MC1414104-40       | 05-14996        | Right Seat Roller Housing | \$157.85 |

| McFarlane Part No. | Spruce Part No. | Description                                       | Price    |
|--------------------|-----------------|---|----------|
| MC1414104-41       | 05-14995        | Left Seat Roller Housing                          | \$113.75 |
| MC1414104-42       | 05-14994        | Right Seat Roller Housing                         | \$102.75 |
| MC1414104-61       | 05-15004        | Right Seat Roller Housing                         | \$177.75 |
| MC1414104-65       | 05-15007        | Right Seat Roller Housing                         | \$193.75 |
| MC1414104-67       | 05-14997        | Left Seat Roller Housing                          | \$188.75 |
| MC1414104-71       | 05-14999        | Left Seat Roller Housing                          | \$253.95 |
| MC1414104-72       | 05-15005        | Right Seat Roller Housing                         | \$258.95 |
| MC1714000-33       | 05-15016        | Right Seat Roller Housing                         | \$207.95 |
| MC1714000-33       | 05-15017        | Left Seat Roller Housing                          | \$217.95 |
| MC1414104-8        | 05-15041        | Universal Bracket for Cessna Seat Roller Housings | \$11.60  |

See the website for complete application information.

AP