#### SNA PA



#### CESSNA BEARING ELEVATOR S1003-29A

FAA-PMA Approved. Please check your Owner's Manual for Eligibility. P/N 06-02538 .....\$2.69

#### CESSNA WINDOW LATCH ASSEMBLIES

208 Window Latch Aircraft Assembly ......... P/N 06-02522 ....... \$628.00 



#### WASHER FUEL BOWL FOR CESSNA AIRCRAFT

Washer Fuel Bowl for Cessna Aircraft - MC0756015-1 P/N 01-01354 .....\$21.50

#### **CESSNA UNIVERSAL JOINT KIT**



A universal joint attaches to each control voke shaft behind the instrument panel. Replacement of the universal joint is recommended if any free motion or rust around the joint pivots is detected. McFarlane also has FAA-PMA approval for the protection sleeve that slides over the universal joint

to reduce vibration wear and act as a safety device. The sleeve is included with every MC0411257 universal joint. Each convenient kit includes nuts and two bolt sizes; only two of the four bolts provided are required when installing the universal joint......P/N 05-22942 .......\$345.00

#### SEE OUR WEBSITE FOR AIRCRAFT ELIGIBILITY LIST. **CESSNA CITATION MAIN GEAR DOOR HINGE PIN**

Cessna Citation main gear door hinge pin. Model 550 and 560. PMA P/N 05-12492 ..... \$36.50

#### CESSNA O-RING NOSE STRUT

MCS1628-329 Cessna O-Ring Nose Strut. FAA-PMA. P/N 06-01586 ..... \$2.65

#### S2418-1 CESSNA SCRAPER RING NOSE STRUT

#### **BRASS SHIM TORQUE LINK FAA-PMA APPROVED**

Eliminates undampened torque link motion to prevent shimmy

Part No.	Cessna Part No.	Thickness	Price ea
05-00429	S1450-6B14-010	.010"	\$3.95
05-00430	S1450-6B14-007	.007"	\$3.95
05-00431	S1450-6B14-005	.005"	\$3.95

#### **CESSNA BEARING FIN S1004-42A**

FAA-PMA Approved. Please check your Owner's Manual for Eligibility. ........P/N 06-02539 ...........\$18.75

**CESSNA SPACERS** Spacer sleeve: made of aluminum alloy 2024 overall

P/N 06-00639 ...... \$0.25

#### CESSNA STUDS

Spruce

Prices Subject to Change Without Notice - Valid as of June 1, 2023.

S115-32 Cessna Stud .....P/N 06-02

McFarlane

2841 <b>\$1.55</b>	Direct repla

ROLLEF

### Description Price

Part No.	Part No.	•	
MC0700645-1	05-15011	Left Seat Roller Housing	\$262.95
MC0700645-2	05-15010	Right Seat Roller Housing	\$274.95
MC0700645-3	05-15009	Left Seat Roller Housing	\$274.95
MC0700645-4	05-15008	Right Seat Roller Housing	\$262.95
MC1200603-38	05-15012	Right Seat Roller Housing	\$48.65
MC1200603-38	05-15013	Left Seat Roller Housing	\$48.80
MC1200603-41	05-15015	Left Seat Roller Housing	\$233.95
MC1200603-42	05-15014	Right Seat Roller Housing	\$82.75
MC1414104-25	05-15001	Left Seat Roller Housing	\$200.75
MC1414104-39	05-15002	Left Seat Roller Housing	\$108.99
MC1414104-40	05-14996	Right Seat Roller Housing	\$108.99



#### 150/152 SEAT RAIL SCREW KIT SR150-SCREW-KIT

This is screw kit specifically for the Cessna 150/152 seat rails. This #10 Structural Screw Kit contains all screws and nuts required to

install four seat rails. Kit Contains: 40 MS27039-1-08 Screw 10-32 x .531, 2 MS27039-1-09 Screw 10-32 x .594, 2 MS27039-1-17 Screw 10-32 x 1.094, 40 MS21044N3 Nut, Nylon Lock...... P/N 05-04107......\$27.50



# LOCK WASHER

One side is embossed with a surface texture for improved locking strength and to make sure the washer does not slip while tightening. FAA approved using stronger material than the original, allowing the standard washer to be eliminated. \*Designed with six tabs instead of two.\*Cessna 180, 182, 185, 188, 205, 206, 207, 210, 310, 200, 411, and 414, model circuit

320, 411, and 414 model aircraft......P/N 05-01742 ......\$10.85





We now have the improved fuel vent lines approved for many additional Cessna 150, 172, and 175 series aircraft. Parts ending with a "K" suffix indicate the inclusion of a rubber grommet, p/n MS3548-14, and hose, p/n MCS1495-8. Features: • Stops environmental and asphalt damage . Fly with known full tanks • Extends useful range • FAA-PMA direct


05-06983

05-06984

٦.	replacement – No STC or 337 for needed			
1	Model	Part No.	Price	
ľ	MC0523559-6	05-06982	\$287.95	
5	MC0523559-6K	05-06983	\$288.95	
1	MC0523559-8	05-06984	\$287.95	
	MS0523559-8K	05-06985	\$243.95	
CONA C1070 1 CTUD TDIMOUNT				

#### CESSNA S1878-1 STUD TRIMOUN I Cessna S1878-1 Stud Trimount. P/N 06-02839 ......\$1.10 MC1243426-2 UPPER

## TORQUE LINK ASSEMBLY





FAA-PMA direct replacement. Eligible for all Cessna Caravan 208,208B. Selective fit components. Cadmium plated stainless pins and anodized aluminum hinges for better corrosion resistance. No looseness in the hinge to start vibration wear. Part No. Price

SPOILER


C

HINGES

\$164.75

\$179.75





machined replacement torque links are designed to meet the rigors of the Alaskan bush. Part Number Price

05-12926	\$804.00
05-12925	\$762.00
	05-12926



SENGER DU UH 3 FOR CESSNA CARAVAN

Engineered for increased longevity and constructed solely from aluminum. No more delamination.

acement for all positions, Cessna P/Ns 2617076-1 (lower), 2617076-

McFarlane Part No.	Spruce Part No.	Description	Price
MC1414104-41	05-14995	Left Seat Roller Housing	\$104.95
MC1414104-42	05-14994	Right Seat Roller Housing	\$103.85
MC1414104-61	05-15004	Right Seat Roller Housing	\$185.75
MC1414104-65	05-15007	Right Seat Roller Housing	\$201.95
MC1414104-67	05-14997	Left Seat Roller Housing	\$194.75
MC1414104-71	05-14999	Left Seat Roller Housing	\$265.95
MC1414104-72	05-15005	Right Seat Roller Housing	\$269.95
MC1714000-33	05-15017	Left Seat Roller Housing	\$217.95
MC1414104-8	05-15041	Universal Bracket for Cessna Seat Roller Housings	\$37.85
See the we	ebsite for c	omplete application informatio	n

## WWW.AIRCRAFTSPRUCE.COM