

CESSNA/PIPER VERNIER ASSIST CONTROLS



Vernier-Assist for non-certified aircraft and an extended line of FAA-PMA approved controls, the breakthrough design is now approved on throttle controls for Cessna, Piper, Beechcraft, Grumman, and Bellanca.

These light weight controls use a patented roller action and do not use a positive lock thread engagement. Coarse adjustments are made by pushing the knob inwards or pulling the knob outwards. Fine adjustments are made by rotating the knob clockwise or counter-clockwise. For extreme conduit routing or heavy carburetor load installation, slight inward or outward assist pressure could be required during rotation.

Part Numbering Note:

Part numbers for Vernier-Assist™ are the same as McFarlane's original push-pull FAA-PMA approved controls, except the "MC" prefix changes to "MCVA".

AP

OEM P/N	Aircraft	Part No.	Price
MCVA565-549-021	172: R, S	05-26515	.
MCVAC299505-0102	172: I, K, L, M, F172M	05-26516	.
MCVA9863056-3	172: N, P, Q, F172N, F172P	05-26517	.
MCVA9863056-1	152: A152, F152, FA152	05-26520	.
MCVAC299505-0202S	150: H, J, K, L, M A150: K, L, M F150: H, J, K, L, M FA150: K, L FRA150: L, M	05-26521	.
MCVAC299505-0101	P206: C, D, E TP206: C, D, E TU206: C, D, E, F U206: C, D, E, F 210: H, J, K, L T210: H, J, K, L	05-26522	.
MCVA9863056-2	206: TU206G, U206G 210: N, P210N, T210N	05-26523	.
MCVAS1222-1S	180: A, B, C, D, E, F, G 182: A, B, C, D	05-26524	.
MCVA12693-04	PA-22 PA-28: -140, -150, -160, -180, -235	05-26525	.
MCVA9863053-20	152: A152, F152, FA152	05-26526	.
MCVA9863053-15	172: N, F172N	05-26527	.
MCVAC299505-0205	182: 182P	05-26528	.
MCVAC299505-0201S	180: H, J 182: L, M, N, P	05-26529	.
MCVA565-549-031	182: S, T, T182T	05-26530	.
MCVAS1222-2S	170 B 172: A, B, C, D, F172D	05-26531	.
MCVA9863055-9	180K 182, R, F182Q	05-26532	.
MCVAS1222-15S	172: E, F(T-41A), G, H(T-41A) F172: E, F, G, H	05-26533	.
MCVAS1222-6S	182: E, F, G	05-26534	.
MCVAC299505-0501	185 - A185: E, F	05-26535	.
MCVA507005-3	AA-5: AA-5B	05-26536	.
MCVA9863053-13	206: TU206G, U206G 210: P210N, T210M	05-26537	.
MCVA9863056-8	172: 172RG	05-26540	.
MCVAC299505-0301	177: A, B 185: A185E	05-26541	.
MCVAS1222-11S	150: A, B, C, D, E, F, F150F	05-26542	.
MCVAS1222-13S	180: H 182: J, K	05-26543	.
MCVA9863053-5	180: K 182: Q, F182P, F182Q	05-26544	.
MCVAS1222-10A	206: P206- A, B, TP206- A, B, TU206- A, B, U206- A, B 210: E, F, G, T210- F, G	05-26545	.
MCVA9863056-5	185: A185F	05-26546	.

OEM P/N	Aircraft	Part No.	Price
MCVAC299505-0401	177: RG, F177RG	05-26547	.
MCVA0411091-7	120, 140 140: A 150	05-26548	.
MCVA565-549-041	206: H, T206H	05-26549	.
MCVAS1219-1	205: 210-5(205), 210-5A(205A) 206 210: B, C, D	05-26550	.
MCVA9863056-6	182: FR182, R182	05-26551	.
MCVA507005-2	AA-5: AA-5A	05-26552	.
MCVA9863056-7	182: T182, TR182	05-26553	.
MCVAS1222-14S	150: G, F150G	05-26554	.
MCVA0411091-2	170: A, B	05-26556	.
MCVA9863053-17	185: A185F	05-26557	.
MCVA9863056-4	207: A, T207A	05-26558	.
MCVAS1222-19	177	05-26559	.
MCVA69530-02	PA-32: PA-32-300	05-26560	.
MCVA9863055-10	FR172K, R172K	05-26561	.
MCVA1213228-2	210: 210A	05-26562	.
MCVAS1294-1	185: A, B, C, D, E, A185E	05-26563	.
MCVAS1222-25A	207: T207	05-26564	.
MCVAS1222-4	172: FP172, P172D 175: A, B, C	05-26565	.
MCVA9863053-10	172: FR172K, R172K	05-26566	.
MCVA9863053-16	207: A, T207A	05-26567	.
MCVAC299505-0203S	172: F172- H, K, L, M	05-26568	.
MCVAC299505-0204S	172: FR172- F, G, H, J	05-26569	.
MCVA0411091-4	190 195A, B, 195 (LC-126A, B, C)	05-26570	.
MCVAC299513-0101	210: R, P210R, T210R	05-26571	.
MCVA0411091-27	175	05-26572	.
MCVA455-139	PA-20, PA-22	05-26573	.
MCVA507005-1	AA-1: A, B, C	05-26574	.
MCVA565-549-013	177: B	05-26575	.
MCVAS191783-18	17-30: A, 17-31A, 17-31ATC	05-26576	.
MCVA0411091-30	175	05-26577	.
MCVA1213228-3	185	05-26578	.
MCVA35-944046-7	33 / 35 / 36	05-27277	.