Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

TCDS HOLDER	MODEL	TCDS NUMBER	CERTIFICATION BASIS	INSTALLATION INSTRUCTIONS	ICA
American Champion (Bellanca) (Champion) (Aeronca)	7AC, 7ACA, S7AC, (L-16A) 7BCM, (L-16B) 7CCM, S7CCM, 7DC, S7DC, 7EC, S7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCAA, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 7KC, 7KCAB	A-759	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
American Champion (Bellanca) (Champion)	8KCAB, 8GCBC	A21CE	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

American Champion (Bellanca) (Trytek) (Aeronca)	11AC, S11AC, 11BC, S11BC	A-761	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
American Champion (Bellanca) (Trytek) (Aeronca)	11CC, S11CC	A-796	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

AeroSedan, LLC (Rogers) (Mitchell) (Aeronca)	15AC, S15AC	A-802	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Textron Aviation, Inc. (Cessna)	120, 140	A-768	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Textron Aviation, Inc. (Cessna) (when converted to conventional gear)	140A	5A2	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Textron Aviation, Inc. (Cessna) (when converted to conventional gear)	150,150A, 150B, 150C,150D, 150E, 150F, 150G, 150H, 150J,150K, A150K, 150L, A150L, 150M, A150M, 152, A152	3A19	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Textron Aviation, Inc. (Cessna)	170, 170A, 170B	A-799	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Textron Aviation, Inc. (Cessna) (when converted to conventional gear)	172, 172A,172B,172C, 172D, 172E, 172F (USAF T-41A), 172G, 172H (USAF T-41A), 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172R, 172S	3A12	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Textron Aviation, Inc. (Cessna) when converted to conventional gear	175, 175A, 175B, 175C	3A17	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Topcub Aircraft, Inc.	CC18-180, CC18-180A	A00006SE	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Cub Crafters	CC21-180	A00057SE	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Cub Crafters	CC19-180, CC19-215	A00053SE	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

FS2000 Corp.	L-14	760	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
FS2001 Corp.	J5A (Army L-4F), J5A-80, J5B (Army L-4G), J5C, AE-1, HE-1	A-725	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

FS2002 Corp.	PA-14	A-797	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
FS2003 Corp.	PA-12, PA-12S	A-780	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

STOL Aviation	S-1B1 (Army L-6, XL-6), S-1B2	A-754	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Luscombe	8, 8A, 8B, 8C, 8D, 8E, 8F, T-8F	A-694	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Piper Aircraft, Inc.	J3C-40, J3C-50, J3C-50S, J3C-65, J3C-65S, PA-11, PA-11S	A-691	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Piper Aircraft, Inc.	J3F-50, J3F-50S, J3F-60, J3F-60S, (Army L-4D) J3F-65, J3F-65S	A-692	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Piper Aircraft, Inc.	J3L, J3L-S, J3L-65 (Army L-4C), J3L-65S	A-698	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Piper Aircraft, Inc.	J4, J4A, J4A-S	A-703	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Piper Aircraft, Inc.	J4E (Army L-4E)	A-740	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Piper Aircraft, Inc.	PA-15	A-800	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Piper Aircraft, Inc.	PA-16, PA-16S	1A1	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Piper Aircraft, Inc.	PA-17	A-805	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Piper Aircraft, Inc.	PA-18, PA-18S, PA-18 "105" (Special), PA-18S "105" (Special), PA-18A, PA-18 "125" (Army L-21A), PA-18S "125", PA-18AS "125", PA-18 "135" (Army L-21B), PA-18A "135", PA-18S "135", PA-18A "135", PA-18S "150", PA-18A "150", PA-18S "150", PA-18AS "150", PA-19 (Army L-18C), PA-19S	1A2	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Piper Aircraft, Inc.	PA-18A (Restricted), PA-18A "135" (Restricted), PA-18A "150" (Restricted)	AR-7	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Piper Aircraft, Inc.	PA-20, PA-20S, PA-20 "115", PA-20S "115", Pa-20 "135", PA-20S "135"	1A4	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Piper Aircraft, Inc. (when converted to conventional gear)	PA-22, PA-22-108, PA-22-135, PA-22S-135, PA-22-150, PA-22S-150, PA-22-160, PA-22S-160	1A6	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Aviat Aircraft, Inc.	S-1S, S-1T, S-2, S-2A, S-2S, S-2B, S-2C	A8SO	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Aviat Aircraft, Inc.	A-1, A-1A, A-1B, A-1C-180, A-1C-200	A22NM	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Taylorcraft, Inc.	(Army L-2G) BF, BFS, BF-60, BFS-60, BF-65, BFS-65, (Army L-2K) BF12-65, BFS12-65	A-699	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Taylorcraft, Inc.	BL, BLS, (Army L-2F) BL-65, BLS-65, (Army L-2J) BL12-65, BLS12-65	A-700	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Taylorcraft 2000, LLC.	BC, BCS, BC-65, BCS-65, BC12-65 (Army L-2H), BCS12-65, BC12-D, BCS12-D, BC12-D1, BCS12-D1, BC12D-85, BCS12D-85, BC12D-4-85, BCS12D-4-85	A-696	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Taylorcraft 2000, LLC.	19, F19, F21, F21A, F21B, F22, F22A, F22B, F22C	1A9	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Univair Aircraft Corporation (Stinson)	108, 108-1, 108-2, 108-3, 108-5	A-767	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Textron Aviation, Inc. (Cessna)	180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K	5A6	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Textron Aviation, Inc. (Cessna) (when converted to conventional gear)	182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182S, 182T, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, T182, T182T	3A13	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Textron Aviation, Inc. (Cessna)	185, 185A, 185B, 185C, 185D, 185E, A185E, A185F	3A24	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision

Keller Engineering Group, LLC. 18714 Mink Creek Chugiak, Alaska 99567 Approved Model List (AML) Number: SA02553AK Date of Issuance: August 30, 2021

Textron Aviation, Inc. (Cessna)	188, 188A, 188B, A188, A188A, A188B, T188C	A9CE	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision
Pacific Aerospace Ltd	FBA-2C, FBA-2C1, FBA-2C2, FBA-2C4, FBA-2C4T	Α7ΕΑ	14 CFR Part 23, amendment 23-55	Installation Instructions – Bolt- on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 1/23/2021, or later FAA approved revision	Instructions for Continued Airworthiness - Bolt-on Tailwheel Shimmy Dampener for Scott & ABI 3200 & 3400 Series Tailwheel Assemblies, revision IR, dated 02/02/2021, or later FAA accepted revision