

HTL Pneumatic Reservoirs (Cont.):

| Part Number | Core Charge | Notes |
|-------------|-------------|--|
| 9914479-5 | | 24 Yr Service Life: Hydro every 3 Yrs Same as 40005338-5 |
| 9914678-2 | | 24 Yr Service Life: Hydro every 3 Yrs Same as 40005370-1 |
| 9914678-3 | | 24 Yr Service Life: Hydro every 3 Yrs Same as 40005369-2 |
| 9914678-4 | | Same as 40005399-1 |

* Various Dash Numbers Are Available
Customer Property Overhaul Only.

Tavco Pneumatic Reservoirs:

| Part Number | Core Charge | Notes |
|--|-------------|--|
| 23111218 Hydro Test Hydro Test & X-Ray | | X-Ray on the 9th & 12th Yr Scrap on 15th Yr |
| 23111321-* Hydro Test Hydro Test & X-Ray | | X-Ray on the 9th & 12th Yr Scrap on 15th Yr |
| 23111425 Hydro Test Hydro Test & X-Ray | | X-Ray on the 9th & 12th Yr Scrap on 15th Yr |
| 9912103-1 Hydro Test Hydro Test & X-Ray | | X-Ray on the 9th & 12th Yr Scrap on 15th Yr |

Customer Property Overhaul Only.
* Various Dash Numbers Are Available

Landing Gear Actuators:

Beechcraft Landing Gear Actuators (Overhauled):

| Part Number | Core Charge | Notes |
|---------------|-------------|----------------------|
| 115-820046-5 | | No Longer Repairable |
| 50-810164-17 | 5,000.00 | |
| 50-810164-18 | 5,000.00 | |
| 50-820208-5 | 5,000.00 | |
| 99-810057-651 | 5,000.00 | S/A -653 |
| 99-810057-652 | 5,000.00 | S/A -654 |
| 99-810057-653 | 5,000.00 | |
| 99-810057-654 | 5,000.00 | |