




RTX



California Power Systems can supply all the parts you require worldwide. However, if you need service in the Western United States we manage a network of ROTAX factory trained technicians, or Independent Repair Centers (IRC). To find a local certified technician, please visit our website at www.cps-parts.com/cps/repairstations.html, or call our technical support line 951-549-7786.

ROTAX FACTORY APPROVED TRAINING COURSES:

CPS holds classes throughout the year at our facility in Chino California, for more information about the classes and the current schedule visit www.cps-parts.com/menus/rtx/zclasses.html.

HOW TO BECOME AN INDEPENDENT REPAIR CENTER:

For information about becoming a certified ROTAX IRC or trained technician, contact CPS at 800-247-9653 or info@cps-parts.com.

OVERHAUL SERVICES

582 UL ENGINES

Engine	Part No.	Exhaust	Carburetors	B-Gearbox	Part No	E-Gearbox	Part No
582 UL WITH SIDEMOUNT EXHAUST	15-08209-1	881-636	2	1:2.00	15-04496	1:2.62	15-07815
582 UL WITH STRAIGHT EXHAUST	15-08209-2	881-631	2	1:2.24	15-07774	1:3.00	15-07816
582 UL WITH 90° (EIPPER EXHAUST)	15-08209-3	881-634	2	1:2.58	15-05342	1:3.47	15-07817
						1:4.00	15-07818

912 / 914 UL ENGINES

Engine	Part No.	Exhaust	Carburetors	Gearbox	Expansion Tank	Oil Tank	CHT Sensors	Oil Temp Sensor	Oil Press Sensor	Ring Mount
912 UL, 80 Horsepower	15-07717	No	Yes	Yes, 2.27:1, w/o Clutch	Yes	Yes	2	1	1	No
912 ULS, 100 Horsepower	15-07722	No	Yes	Yes, 2.43:1 with Clutch	Yes	Yes	2	1	1	No
914 UL, 115 Horsepower, Turbocharged	15-07723	Yes	Yes	Yes, 2.43:1 with Clutch	Yes	Yes	2	1	1	Yes

912 / 915 ISERIES ENGINE

Engine	Part No.	Exhaust	Carburetors	Gearbox	Expansion Tank	Oil Tank	CHT Sensors	Oil Temp Sensor	Oil Press Sensor	Ring Mount
912 IS, Sport 100 Horsepower	15-08635	Yes	Fuel Injected	Yes, 2.43:1 with Clutch	Yes	Yes	4	1	1	Yes
915 IS Turbo, 140 Horsepower	15-09449	Yes	Fuel Injected	Yes	Yes	Yes	4	1	1	Yes

OVERHAUL PARTS

150 Hour Inspection

300 Hour Overhaul

Engine	Gasket Set	Gasket Set	Gasket Assembly
503 UL	994-236	994-236	996-441
582 UL/90	886-230	886-230	887-051
582 UL/99	886-232	886-232	887-051

**CALL BRYAN TOEPFER AT 1-800-247-9653 OR
EMAIL: BRYANTOEPFER@CPS-PARTS.COM FOR PRICE AND AVAILABILITY.**