



- A For version 2 with narrow dog gear (22 mm / 0.87 in.)
- B For version 3 with narrow dog gear (22 mm / 0.87 in.)
- C For version 4 with narrow dog gear (22 mm / 0.87 in.)
- D For version 2 with wide dog gear (27 mm / 1.06 in.); For 914 use only from following engine S/N: 914 F: 4420164 / 914 UL: 4417791
- E For version 3 with wide dog gear (27 mm / 1.06 in.); For 914 use only from following engine S/N: 914 F: 4420164 / 914 UL: 4417791
- F For version 4 with wide dog gear (27 mm / 1.06 in.); For 914 use only from following engine S/N: 914 F: 4420164 / 914 UL: 4417791
- G Replacement for 887701 with wide dog gear
- H Replacement for 887706 with wide dog gear
- I Replacement for 887711 with wide dog gear
- J Replacement for 887680 with wide dog gear
- K Replacement for 888565 with wide dog gear

- a Drive gear 22 T. and reduction gear 50 T. are paired and must be replaced together and marked with S/N. See SL-912-002 resp. SL-914-002.
- b Drive gear 21 T. and reduction gear 51 T. are paired and must be replaced together and marked with S/N. With wide dog gear (27 mm / 1.06 in.); See SL-912-002 resp. SL-914-002; For 914 use only from following engine S/N: 912 S: starting with serial production / 912 ULS: starting with serial production / 914 F: 4420164 / 914 UL: 4417791
- c For model 2 marked with S/N
- d For model 3 marked with S/N
- e For model 4 marked with S/N
- f For gear sets part no. 886125 and 886517; (narrow versions)
- g For gear set part no. 886518; (wide version)

- h Drive gear 21 T. and reduction gear 51 T. are paired and must be replaced together and marked with S/N. With thin dog gear (22 mm / 0.87 in.); See SL-912-002 resp. SL-914-002; For 914 use only up to S/N: 914 F: 4420163 / 914 UL: 4417790
- i Do not use at version with auxiliary alternator; only available as a set (includes 6 pieces).
- j Only when a governor is used; Version without governor: 2x940.591; with governor: see chapt. 61-20-00
- l Dog hub with extended hub
- m With additional bores to drain lead
- n Increased support bearing diameter
- o See SL-912-002 current issue
- p Gearbox with oil spray nozzle. Starting with Gearbox SN 74000.
- q Replaced by hex. torx screw part no. 940077.