

# GASKETS



**TCM MAGNETO GASKET 649954**  
P/N 05-11920 .....\$1.10

**TCM 649989 OIL COOLER GASKET**

P/N 08-13252 .....\$2.15



**FUEL PUMP GASKET - 649962**

P/N 08-13567 .....\$2.40

**PT-6 NOZZLE GASKET**

PT-6 Nozzle Gasket. Replacement part for Pratt & Whitney 3029566.

P/N 05-15099 .....\$2.75





**LYCOMING PROP GOVERNOR GASKET**

Propeller governor gasket for Lycoming O-320 A & E Series engines. ....P/N 72053 .....\$1.52

**LW12681 LYCOMING MAGNETO GASKET**

Lycoming Magneto Gasket model # LW12681. For Lycoming 0320 all letter designations EXCEPT the "H" series.

P/N 08-00285 .....\$1.70



**TCM OIL GASKETS**

TCM 654553 Gasket, 12 Bolt Oil Cooler Gaskets for Continental Engines. (Old style crankcase).....P/N 06-02793 .....\$22.95  
TCM 654555 Oil Cooler Gasket for Continental Engines .....P/N 06-02162 .....\$15.70

## 1/8 INCH SILICONE VALVE COVER GASKETS

Valve cover gaskets are manufactured from a silicone rubber compounded especially for lubricating oil resistance and low compression set. It has a recommended temp. operating range of -67 to 446 F and will remain flexible while operating in the noted temp. range. One of the biggest benefits of replacing the factory cork gaskets with the Silicone rubber gaskets is that they are reusable and are easy to work with and are 1/8" thick silicone rubber.


Image	OEM Part No.	Application	PN	Price
	75906-SP	Lycoming O-235, O-290, O-320, IO320, O-360, IO-360, HIO-360, O-480, O-540, IO-540	05-11181	<b>\$10.50</b>
	71450	Lycoming IO-540-B, E, M series, TIO/LTIO-540-A	05-11182	<b>\$13.50</b>
	67193	Lycoming IO-360, VO/GO-435, GO-480, IO-540, VO-540, TIVO-540, IO-720	05-11183	<b>\$10.50</b>
	632310	Continental IO-360, TSIO-360, LTSIO-360	05-11184	<b>\$7.50</b>
	632459	Continental GTSIO-520 series, IO-550-G, TSIO-520-BE	05-11185	<b>\$7.50</b>
	530162	Continental A-65, C-75, C-85, C-90, C-125, C-145, O-200, O-300, GO-300	05-11186	<b>\$10.50</b>

## "O" SERIES LYCOMING VALVE COVER GASKETS

Note: 08-05882 is similar to 67193 and RG-67193 but not FAA Approved for Certified Aircraft. 08-01187 is similar to 75906 and RG-75906 but not FAA Approved for Certified Aircraft.

These homebuilder's Lycoming valve cover gaskets replace the original cork gaskets which come standard on Lycoming O-235, O-320 and O-360 engines. These new gaskets are molded from high temperature silicone rubber and do not harden over time so they can be re-used again and again. This hi-tech silicone rubber offers a much lower compression set, so it is superior at maintaining an oil-tight seal for the life of the engine. NOT FAA approved. For experimental aircraft only.

P/N 08-01187 .....\$5.50



## ANGLED VALVE "IO" SERIES LYCOMING VALVE COVER GASKETS

These gaskets are for the fuel injected "IO" series, sometimes referred to as the Angle Valve cylinder Lycoming, as well. these gaskets are molded from the same high-temperature silicone rubber as the "O" series gaskets above, and do



not harden over time, so they can be reused again and again. This hi-tech silicone rubber offers a much lower compression set, so it is superior at maintaining an oil-tight seal for the life of the engine. They are not FAA approved and are not manufactured under a PMA. These are similar to Lycoming part number 67193 used on Angled valve Lycoming engines IO-360, IO-540, IO-720..... P/N 08-05882 .....\$6.85

EP