

# BENDIX-SCINTILLA MAGNETOS

## BENDIX

### BREAKER ASSEMBLIES



**Early S4, S6 Mags**  
 P/N 07-06305 (10-357173) with spring  
 (current production) ..... **\$52.95 Ea.**  
 P/N 07-06306 (10-357174) without spring  
 (current production) ..... **\$49.50 Ea.**

All above breaker assemblies used on either Right or Left Magnetos.  
 Late S4/S6 Mags, S200 Mags\*



### BENDIX MAGNETO GREASE

#10-27165 - Factory recommended lubricant for bearings in Bendix magnetos.  
 1 Lb. Can.....P/N 10-27165 ..... **\$104.90**  
 #10-391200 - For use on distributor block bushing.  
 Provides proper shaft lubrication.  
 8 oz. can.....P/N 10-391200 ..... **\$118.75**

## REPLACEMENT COILS FOR CONTINENTAL ENGINES PER SERVICE BULLETIN NO. 637

TCM Ignition Systems has issued Service Bulletin No. 637 to retire from service certain older coils and rotating magnetos. The Bulletin applies to many S-20, S-200, S-600, and S-1200 series magnetos as identified in this chart. Compliance with this Bulletin is required at the next 100 inspection, annual inspection, or progressive maintenance inspection, whichever comes first. Order by new coil part number.

Magneto Series	Old Coil P/N	Color	New Coil P/N	Color	Our Price
S-20	10-51303	Opaque amber to Dark Purple	10-357164	Bright Red to Dark Red	<b>\$237.95</b>
	10-76384				
	10-160886				
S-20	10-163172	Opaque Amber to Dark Purple	10-357165-1	Bright Red to Dark Red	<b>\$207.95</b>
S-200	10-163209				
	10-160887				
S-1200	10-349271	Opaque Amber	10-391088-1	Blue to Olive Green to Black	<b>\$269.95</b>

### ALTERNATOR FILTER

Replacement part for existing alternator filters. Wire won't break at the case and its clamp is made from heavy gauge steel. Double the capacitance compared to OEM alternator filters. For stubborn alternator noise, this Alternator filter combined with the Eliminator (P/N 11-08055) can trap a wide frequency range of electronic noise. Both of these filters have been thoroughly tested under a DO 160D and are FAA/PMA approved.  
 P/N 11-08060 ..... **\$99.95**



### MAGNETO FILTER FAA APPROVED

Lone Star Aviation's Magneto filter (FEED THRU) (Fail Safe Design) attenuates both low and high frequencies of noise generated from bendix magneto ignition systems. The firing of the aircraft spark plugs through the ignition systems harness can cause noise problems and interference to aircraft electronics such as audio panels, radio equipment, navigation equipment, instrumentation, and autopilot systems on board an aircraft. This filter has been used by avionics shops, OEM aircraft manufacturers, and FBO's, to attenuate and suppress pulsating noise generated by their aircraft's magneto systems. The magneto filter is FAA-PMA approved and is compatible with the bendix series S20, S21, S200, D3000, D4000 magneto.

**Features:** • 1000 VDC working voltage, 5000VDC break down voltage  
 • Capacitance: .05 uf-self healing technology • Braided cable is shielded, silver plate over copper, supplied in 8 inch lengths • Heavy duty mounting clamp • Advanced feed through design • Temp. range: -35°C to +80°C • Max. current: 20 amps.....P/N 07-00713 ..... **\$99.95**

### BOGERT AVIATION GROMMET STRETCHER TOOL



Using the Grommet Stretcher is 2-3x's faster when stretching grommets over fittings and plugs. Improves safety because grommets are continuous. Operating Instructions: 4 Simple Steps Saves time and frustration. Insert grommet over end of Grommet Stretching Tool. Squeeze handle to spread the grommet. Insert cable through grommet and release the squeeze on tool handle. Remove the grommet from tool by sliding grommet off the ends.  
 P/N 11-06946 ..... **\$39.95**

### GROUND TERMINAL KITS



For S-20 series mags. Kit No. 10-52306 (AN3105) ..... **\$33.85**

Reg. No.	Part No.	No. Req.	Description
1	10-30299	1	NUT - Coupling (Ground Terminal)
2	10-56507	1	CROMMET Assy.(Ground Terminal)
3	10-3383	1	FERRULE - Inner (Ground Wire)
4	10-25725	1	SLEEVE - Insulating (Ground Wire)



For 20 series mags. Kit No. ....P/N 10-52305 ..... **\$128.75**

Reg. No.	Part No.	No. Req.	Description
1	10-37669	1	NUT - Coupling (Ground Terminal)
2	10-7030	1	FERRULE - Outer (Ground Wire)
3	10-7029	1	FERRULE - Inner (Ground Wire)
4	10-37668	1	SLEEVE - Insulating (Ground Wire)
5	2-155	1	WASHER - Ground Wire Contact

### TCM/BENDIX IMPULSE COUPLINGS

Part No.	Price
10-40307	<b>\$577.00</b>
10-40309	<b>\$635.00</b>
10-40314	<b>\$638.00</b>
10-40315	<b>\$700.00</b>

Core charge applies

### TCM/BENDIX CAM ASSEMBLIES

Part No.	Price
10-40166-6	<b>\$397.00</b>
10-40167-4	<b>\$386.00</b>
10-40167-6	<b>\$419.00</b>

Core charge applies

SEE WEBSITE FOR MORE TCM PARTS!