

TEMPEST DRY AIR PUMPS



TEMPEST TORNADO 3000 DRY AIR PUMPS

New revolutionary LRT oil drain, patent pending feature is designed to drain oil, caused by a leaking Garlock Seal, before it reaches the drive coupler. Provides a tell tale leak path. Closed front ends, designed to eliminate oil and oil residues from entering into the pump. Helps prevent pump failures caused by oil entering into the drive mechanism or rotor and vanes. 3 year 1300 hour warranty
 Tempest Tornado 3000 Model AA3215CC..... P/N 10-00609...**\$459.00**
 Tempest Tornado 3000 Model AA3216CW P/N 10-00610...**\$457.00**
 Tempest Tornado 3000 Model AA3215CC-9.... P/N 10-00611...**\$457.00**
 Tempest Tornado 3000 Model AA3226CW P/N 10-06598...**\$498.00**

VACUUM PUMP COOLING SHROUDS FOR AIRBORNE AND TEMPEST



Cooling shrouds have been proven to reduce pump operating temperature and therefore extend service life. Testing has proven reduction in operating temperature by as much as 15%. Saves money - extends service life of dry air pumps. AA20T fits all 200/240 series pumps. AA40T fits all 400 series pumps. Sigma - Tek® pumps are not eligible.
 AA207P/N 10-02796**\$97.85**
 AA40TP/N 10-02797**\$114.75**

VACUUM PUMP APPLICATION

See www.aircraftspruce.com for complete listing of vacuum pump applications for most general aviation aircraft.

TEMPEST WEAR INDICATOR TOOL KIT



Tempest Wear Indicator Tool Kit.
 Kit includes: 3 Star Lockwashers (82-50122-2A2), 3 Hole Plugs (82-50122-2A1), 1 WIP Tool (82-501222A6T)P/N 10-04814**\$64.85**

TEMPEST ELECTRIC AUXILIARY DRY AIR PUMPS



Electric auxiliary dry air pumps are recommended for single engine aircraft flown in IFR conditions as a back-up in the event the primary vacuum pump fails. These pumps are FAA-PMA approved as direct replacements for Airborne pumps previously installed under STC eligibility and STC approval for these pumps for many additional aircraft is pending.
 28VECElectric Auxiliary Dry Air Pump Model AA4A2-1 P/N 10-00585 **\$2,093.00**
 14VECElectric Auxiliary Dry Air Pump Model AA4A3-1 P/N 10-00584 **\$2,310.00**

TEMPEST DRY AIR PUMPS



Tempest dry air pumps, from Aero Accessories, are 100% new production and use all new components. They are FAA-PMA approved replacements for like and similar models on many installations. These pumps are available in the 200, 240, and 400 series.
 The AA215CC series come with a 1-year, unlimited hour warranty and the AA241CC, AA242CW, and the AA441CC and AA442CW series come with a 1-year, 500 hour warranty. Warranties expire 2-years from date of manufacture. **Addition Core Charge applied to Overhauled Pumps**
***Core Rebate available for new pumps.**



TEMPEST DRY AIR PUMPS - OVERHAULED

Model	Description	Part No.	Price
215CCWIP	Overhauled Dry Air Pump w/WIP	10-24000-1	\$316.00
216CWWIP	Overhauled Dry Air Pump w/WIP	10-24600-1	\$316.00
241CC	Overhauled Dry Air Pump	10-24700-1	\$520.00
243CC-13	Overhauled Dry Air Pump	10-01969	\$525.00
243CC-15	Overhauled Dry Air Pump	10-01968	\$525.00
242CW	Overhauled Dry Air Pump	10-24800-1	\$520.00
244CW-4	Overhauled Dry Air Pump	10-01971	\$525.00
244CW-10	Overhauled Dry Air Pump	10-01972	\$700.00
441CC-OH	Overhauled Dry Air Pump	10-23500-1	\$699.00
441CC-3	Overhauled Dry Air Pump	10-01974	\$688.00
441CC-7	Overhauled Dry Air Pump	10-01975	\$725.00
441CC-9	Overhauled Dry Air Pump	10-01977	\$655.00
441CC-11	Overhauled Dry Air Pump	10-01978	\$688.00
441CC-17	Overhauled Dry Air Pump	10-01979	\$725.00
441CC-23	Overhauled Dry Air Pump	10-01980	\$655.00
442CW	Overhauled Dry Air Pump	10-23600-1	\$699.00
442CW-4	Overhauled Dry Air Pump	10-01981	\$715.00
442CW-6	Overhauled Dry Air Pump	10-01982	\$715.00
442CW-8	Overhauled Dry Air Pump	10-01983	\$715.00
442CW-10	Overhauled Dry Air Pump	10-01984	\$688.00
442CW-12	Overhauled Dry Air Pump	10-01146	\$734.00
442CW-14	Overhauled Dry Air Pump	10-01985	\$688.00
442CW-20	Overhauled Dry Air Pump	10-01986	\$688.00

TEMPEST DRY AIR PUMPS - NEW

Model	Description	Part No.	Price
AA241CC	New Dry Air Pump	10-24700	\$770.00
AA243CC-13	New Dry Air Pump	10-01987	\$803.00
AA243CC-15	New Dry Air Pump	10-01988	\$803.00
AA243CW	New Dry Air Pump	10-24800	\$770.00
AA244CW-4	New Dry Air Pump	10-01989	\$803.00
AA244CW-10	New Dry Air Pump	10-01990	\$803.00
AA3215CC	New Dry Air Pump	10-00609	\$459.00
AA3216CW	New Dry Air Pump	10-00610	\$457.00
AA3215CC-9	New Dry Air Pump	10-00611	\$457.00
AA441CC	New Dry Air Pump	10-23500	\$1,165.00
AA441CC-3	New Dry Air Pump	10-01991	\$1,110.00
AA441CC-7	New Dry Air Pump	10-01992	\$1,145.00
AA441CC-9	New Dry Air Pump	10-01993	\$1,110.00
AA441CC-11	New Dry Air Pump	10-01994	\$1,133.00
AA441CC-17	New Dry Air Pump	10-01995	\$1,110.00
AA442CW	New Dry Air Pump	10-23600	\$1,075.00
AA442CW-4	New Dry Air Pump	10-01996	\$1,110.00
AA442CW-6	New Dry Air Pump	10-01997	\$1,165.00
AA442CW-8	New Dry Air Pump	10-01998	\$1,134.00
AA442CW-10	New Dry Air Pump	10-01999	\$1,132.00
AA442CW-12	New Dry Air Pump	10-02001	\$1,229.00
AA442CW-14	New Dry Air Pump	10-02002	\$1,110.00
AA442CW-20	New Dry Air Pump	10-02003	\$1,110.00

IN