

CESSNA PARTS

Part. No.	Description (cont'd)	Price
06-03325	Spinner Front Plate	\$1,283.00
06-03326	Fastners S3412-105	\$10.50
06-03327	Fastners S3412-108	\$11.75
06-03328	Textron Fuel Cap 100-381005-15	\$1,646.00
06-03329	Body Assembly JMDX36-001	\$764.00
06-03330	Bf Goodrich Aerospace Cleaner (32 Oz)	\$60.80
06-03331	Toggle Switch S1160-1-1	\$186.75
06-03334	Nose Faring 05436079-15	---
06-03336	Float Switch	\$1,598.00
06-03337	Knob Assembly	\$16.50
06-03338	Resistor	\$112.75



CESSNA TRIM CONTROL CHAINS

We carry FAA-PMA approved replacement trim control chains for Cessna 120 through 210 series aircraft. Call the Cessna/Piper parts specialist at Aircraft Spruce (1-877-4-SPRUCE) for assistance in determining the correct chain for your aircraft.

Model No.	Part No.	Price Ea.
ASS2294-25	05-00289	\$4.45
ASS2295-25-185	05-00291	\$339.00
ASS2295-25-249	05-00292	\$219.95
ASS2295-25-43	05-00294	\$66.75
ASS2295-25-47	05-00295	\$98.75
ASS2295-25-61	05-00296	\$141.85
ASS2295-25-63	05-00297	\$286.95
ASS2295-25-67	05-00298	\$159.75
ASS2295-25-70	05-00299	\$25.60
ASS2295-25-71	05-00301	\$40.70
ASS2295A25-111	05-00302	\$32.65
ASS2295P25-113	05-00303	\$159.75
ASS2295P25-155	05-00304	\$182.99
ASS2295P25-159	05-00305	\$109.75
ASS2295P25-185	05-00306	\$55.75
ASS2295P25-321	05-00307	\$171.75
ASS2295P25-47	05-00308	\$50.50
ASS2295P25-55	05-00309	\$67.75
ASS2295P25-59	05-00311	\$42.50
ASS2295P25-63	05-00312	\$70.80
ASS2295P25-67	05-00313	\$92.75
ASS2295P25-69	05-00314	\$120.75
ASS2295P25-71	05-00315	\$125.75
AS0432138-2	05-00316	\$165.75



6260 RETAINING NUT 7/16-20

The retaining nut threads onto the threaded section of the control on the back side of the instrument panel to secure the control. Replacement retaining nut P/n 6260 for all McFarlane MC6350 dual push-to-unlock controls. P/N 05-04581 **\$11.50**



INTER-CYLINDER BAFFLE

Intercylinder Baffles for Teledyne Six Cylinder Engines. Replaces Cessna Part Number 0750135-1 and 0851833-1. P/N 05-02362 **\$70.75**



CESSNA FLAP TRAILING EDGE STIFFENER

Improved Fit to Reduce Skin Stress. The stiffeners are accurately shaped to the same angle that the top and bottom skins come together to completely eliminate the bending stress due to riveting the skins together. FAA/PMA Approved. For application please call or visit our website.

Flap Tracing Edge Stiffener 79.5" P/N 05-00046 **\$87.75**
Flap Tracing Edge Stiffener 116.25" P/N 05-07237 **\$152.75**



RETRACTABLE GEAR BRAKE SWIVEL FOR CESSNA AIRCRAFT

Retractable Gear Brake Swivel for Cessna Aircraft, including O-ring P/N MS28778-3. Replace your leaking Brake Swivel Assembly with an improved assembly that a direct FAA-PMA replacement for the OEM 1280111-1. It's designed to provide a leak-proof swivel point, allowing the landing gear to retract without damaging the brake line. Each assembly undergoes pressure and motion testing P/N 05-27274 **\$1,229.00**

CESSNA SEAT RELEASE CONTROL ASSEMBLY

Seat Release Control Assembly that incorporates many design improvements. This control assembly will last significantly longer! • Cessna 172R,S, 182S,T, T182T, 206H, T206H • Lifetime anodized aluminum housing - not cheap plastic • Heavy duty cable and terminal - twice as strong! • Nylon lined conduit tubing ensures your cable will not bind • Fully repairable P/N 05-27276 **\$823.00**

Part. No.	Description	Price
06-03339	Inserts 182D	\$9.50
05-22169	AA1K1-4-8 Fitting	\$88.90
05-22889	Bearing S1004-15A	\$2.25
06-03534	Terminal S1493-2	\$1.40
06-03535	Brackett 0517018-8	\$113.75
1552010-1	Spring	\$6.50
RG65	Grommet	\$43.75
S2800-797	Resistor	\$135.75
50-820038	Retainer	\$31.60
NAS561P12-48	Roll Pin	\$2.15



CESSNA WHEEL PANT MOUNTING PLATES

These FAA-PMA approved mounting plates are anodized for improved corrosion resistance and will save over \$100 compared to factory mounting plates. Approved with partial eligibility for the Cessna 150, 152, and 172. Verify approval for your aircraft with Aircraft Spruce prior to ordering.

Cessna P/N	Aircraft Model	Our P/N	Price Each
0441225-1 (Left)	150/152	05-01497	\$160.85
0441225-2 (Right)	150/152	05-01498	\$160.85
0441220-1 (Left)	172	05-01499	\$111.75
0441220-2 (Right)	172	05-01501	\$87.75

CESSNA CARAVAN BUSHING KITS ELEVATOR AND RUDDER



Cessna has issued several non-mandatory service bulletins and service kits for the rudder and elevator hinge bearings on the Caravan due to a corrosion issue with the needle bearing. The service kits require modification to the hinge structure, not just the bearing itself. The new bearing is a different size than the "original" design, so the mounting hardware is different as well. Because of these structural changes any aircraft that has had the service kits installed cannot use hardware from a non-service kit aircraft. Includes bearings and all attaching hardware. Caravan Elevator Bushing Kit EBC-KT-7 P/N 05-06879 **\$118.75**
Caravan Elevator Bushing Kit EBC-KT-8 P/N 05-06880 **\$474.00**
Rudder Bushing Kit RBC-KT-9 P/N 05-06881 **\$70.85**
Rudder Bushing Kit RBC-KT-10 P/N 05-06882 **\$417.00**



CESSNA CABLE & CHAIN KITS

Complete flight control and trim chain kits for each of the 150 different cable groups required to service all single engine aircraft from the model 120 through model 185 airplanes. It is a tedious and time consuming job to research the part manuals for all of the cables required for a complete aircraft. We carry stock on all of the cables in either Galvanized-Carbon Steel or Stainless Steel. All components are fully traceable, high quality, and proof tested.

Cable & Chain Kit CCTK206H-01S P/N 05-04605 **\$3,088.00**
Cable & Chain Kit CCTK172175-13S P/N 05-04599 **\$3,250.00**
Cable & Chain Kit CCTK206H-01G P/N 05-04604 **\$2,996.00**
Cable & Chain Kit CCTK172175-13 P/N 05-04598 **\$3,362.00**
Cable & Chain Kit CCTK182-13G P/N 05-04601 **\$2,909.00**



CABIN DOOR HINGE ASSEMBLY FOR CESSNA AIRCRAFT

Replacement FAA-PMA cabin door hinge assembly for Cessna 170 / 172 / 175 aircraft. Note: Cessna legacy airplanes, built prior to 1979, feature a door post skin that angles inward (toward the front edge of the door). Aircraft with this bend require a hinge with a 5° bend for correct installation. Later models and new production aircraft do not have this inward angle and use a straight hinge P/N 05-27278 **\$680.00**



MCFARLANE TRIM TAB

ACTUATOR FOR CESSNA AIRCRAFT

This direct replacement trim tab actuator incorporates many design improvements. Longer lasting coatings are utilized for increased service life, smoother operation, and improved corrosion resistance. The Trim Tab Actuator is manufactured with high strength stainless steel alloy that has been nitrocarburized for maximum wear, low friction, and smoother thread operation than the OEM part. The sprocket is made from stronger aluminum, then anodized for wear and corrosion protection. The known problems of original parts have been addressed and resolved with this new design P/N 05-27269 **\$1,808.00**



MCFARLANE RING PACK SUPPORT

• Stainless steel for corrosion resistance • PTFE composite-lined for smoother strut action • Liner holds oil for longer life • Easy on your chrome strut
P/N 05-27106 **\$357.00**