

CESSNA FIBERGLASS REPLACEMENT PARTS

CESSNA 170/172/175

ELEVATORS & STABILIZERS

Here are some of our most popular items. These tips take a good deal of stress in just normal flying circumstances. They're also frequent victims of ramp rash. The original high impact plastic simply can't stand up to the task as well as fiberglass replacements from Stene Aviation. Plus, if these parts ever do withstand damage, they're easily repaired with readily available fiberglass repair kits from your local automotive parts store.



Description	Part No.	Price
172 Horizontal Tip 1963 & on (SA-0532001-93)	05-03744	\$131.90
172/175 Horizontal Tip Straight Tail (SA-0532001-61)	05-03743	\$131.80
172 Elevator Tip 1963 & on LH (SA-0532001-94)	05-03742	\$179.95
172 Elevator Tip 1963 & on RH (SA-0532001-100)	05-03741	\$179.85
172/175 Elevator Tip Straight Tail (SA-0532001-62)	05-03740	\$177.95

STRUT CUFFS

Here's an unbeatable item for renovating your Cessna; a set of replacement strut cuffs. Order just one cuff to replace a damaged original, or get a set of four for a complete replacement.



Description	Part No.	Price
172 Strut Cuff Upper 1973 & on RH (SA-0523047-2)	05-03739	\$126.85
172 Strut Cuff Upper 1973 & on LH (SA-0523047-1)	05-03738	\$128.75
172 Strut Cuff Lower (all models) RH (SA-0522150-2)	05-03736	\$127.75
172 Strut Cuff Lower (all models) LH (SA-0522150-1)	05-03735	\$127.75

WING & DORSAL TIPS

Wing tips are a common victim of hanger and ramp rash. Maybe you thought the plane was going to clear those doors as you wheeled it back into the hanger...the first indication that you were wrong was that grating sound as the wing tip met metal. Here's the solution: replacement fiberglass wing tips from Stene Aviation.



Description	Part No.	Price
172 Wing Tip (small droop) 1968-'72 LH (SA-0523565-29)	05-03726	\$366.00
172 Wing Tip (small droop) 1968-'72 RH (SA-0523565-30)	05-03727	\$366.00
172 Wing Tip (small droop) 1973&on LH (SA-0723200-5)	05-03762	\$372.00
172 Wing Tip (small droop) 1973&on RH (SA-0723200-6)	05-03764	\$367.00
172 Mid-Dorsal (SA-0531012-2)	05-03759	\$135.85
172 Dorsal Tip 1972&on (SA-0531020-1)	05-03760	\$49.95
Cable Covers (SA-0530011-2)	05-03770	\$62.75

RUDDER & VERTICAL FIN CAPS

These parts are a snap to replace on most planes. Please note, indicate if you have a straight tail or a swept tail. It is also important to let us know if your fin cap needs to accommodate a strobe or beacon, and if so, if the light is front-mounted or center-mounted.



Description	Part No.	Price
172 Vertical Fin (no beacon) 1956-'59 (SA-0531001-36)	05-03745	\$175.95
172 Vertical Fin (large beacon) 1956-'59 (SA-0531004-3)	05-03746	\$169.95
172 Vertical Fin (no beacon) 1960-'68 (SA-0531006-33)	05-03747	\$175.15
172 Rudder Top 1969-75 (SA-0533009-1)	05-03752	\$175.85
172 Vertical Fin (small beacon) 1960-'68 (SA-0531009-1)	05-03748	\$175.95
172 Vertical Fin (small beacon) 1969-'75 (SA-0531013-1)	05-03749	\$175.95
172 Rudder Top 1976-'85 (SA-0531006-112)	05-03753	\$175.95
172 Rudder Top 1997&on (SA-0533155-2)	05-03754	\$175.95
172 Vertical Fin (small beacon) 1976&on (SA-0531003-1)	05-03750	\$175.95
172 Rudder Top 1960-'68 (SA-0531006-34)	05-03751	\$175.95
172 Rudder Bottom 1960-'68 (SA-0531006-35)	05-03756	\$163.75
172/175 Rudder Bottom Straight Tail (SA-0531104)	05-03755	\$163.75
172 Rudder Bottom 1969-'97 (SA-0531006-80)	05-03757	\$162.75
172 Vertical Fin (small beacon) (SA-0531033-6)	05-12809	\$165.75
172 Rudder Bottom (SA-0533155-1)	05-12810	\$162.75

GEAR LEG AND BRAKE FAIRINGS

These are excellent items for replacing worn plastic originals. Your fiberglass replacements will be more durable with an improved finish over the original plastics.



Description	Part No.	Price
172 Upper Gear Leg 1971&on RH (SA-1741005-240)	05-03767	\$198.95
172 Upper Gear Leg 1971&on LH (SA-1741005-239)	05-03766	\$198.95
172 Brake Fairing 1974& on LH (SA-0541224-1)	05-03768	\$199.85
172 Brake Fairing 1974&on RH (SA-0541224-2)	05-03769	\$199.85
172 Upper Gear Leg Fairing LH 172R, 172S (SA-1741005-59)	05-12872	\$199.95
172 Upper Gear Leg Fairing RH 172R, 172S (SA-1741005-60)	05-12873	\$201.95

WHEEL PANTS

Replace your original plastic wheel pants with high quality and durable fiberglass replacements. All wheel pants come with a 2" access plug for checking tire pressure. Original hardware is required for mounting.



Description	Part No.	Price
172 Wheel Pant 1974&on RH (SA-0541223-16)	05-03728	\$517.00
172 Wheel Pant 1974&on LH (SA-0541223-17)	05-03729	\$517.00
172 Nose Wheel Pant 1974 & on (SA-0543079-3)	05-03730	\$525.00

SEE WWW.AIRCRAFTSPRUCE.COM FOR COMPLETE LISTING

WWW.AIRCRAFTSPRUCE.COM