

# CARBURETORS



Customer will need to provide core for overhaul in the event that our supplier does not have cores available to overhaul

## REPLACEMENT CARBURETORS FROM MARVEL-SCHEBLER

Carburetor exchange program covers all popular Marvel Schebler/Facet general aviation carburetors. The carburetors are overhauled to the strictest industry standards and carry a full 6 month warranty (from date of installation). Most carburetors are available from stock or within a week and are furnished complete with gaskets.

Due to the various configurations of carburetor installations, we suggest you retain your carburetor core until receiving the exchange unit. This will enable you to transfer all external fittings and installation hardware to the new exchange unit. All cores being returned for credit shall be, as removed from the engine, complete and not disassembled. A reduction in core credit is charged for missing or damaged parts.

- Precision Carburetors
- TCM Fuel Systems
- Flow Dividers
- Fast Turn Time on Overhauls
- Unmatched Quality
- 100% calibration of fuel pumps and servos.
- Precision Fuel Servos
- Romec Fuel Pumps
- FAA/PMA Approved Replacement Parts
- Carburetor Overhaul Quick Kits
- Highly skilled/trained technicians

## LYCOMING CARBURETORS

| Carb. Model | Lycoming P/N | Vendor P/N | Our P/N    | Price |
|-------------|--------------|------------|------------|-------|
| MA-3A       | 61547        | 10-3103-1  | 10-03103-1 | ---   |
| MA-4SPA     | 69250        | 10-3678-12 | 08-06325   | ---   |
| MA-4SPA     | 72394        | 10-3678-32 | 08-06326   | ---   |
| MA-4-5      | 71098        | 10-3878    | 08-06372   | ---   |
| MA-4-5      | 71710        | 10-4164-1  | 08-06373   | ---   |
| MA-4-5      | 66458        | 10-2827    | 07-01405   | ---   |
| MA-4-5      | 66869        | 10-3323    | 07-01411   | ---   |
| MA-3SPA     | 62830        | 10-3565-1  | 07-01413   | ---   |
| MA-4-5      | 69540        | 10-3634    | 07-01415   | ---   |
| MA-4-5      | 71546        | 10-3856-1  | 07-01417   | ---   |
| MA-4-5      | 71685        | 10-3856-12 | 07-01418   | ---   |
| MA-4-5AA    | 71684        | 10-4025-12 | 07-01421   | ---   |
| MA-6AA      | 72407        | 10-4218-1  | 07-01424   | ---   |
| MA-4-5      | 72386        | 10-4329    | 07-01426   | ---   |
| MA-4-5      | 74121        | 10-4404-1  | 08-06376   | ---   |
| MA-6AA      | 73899        | 10-4438-1  | 07-01428   | ---   |
| MA-4-5AA    | 73257        | 10-4495    | 07-01429   | ---   |
| MA-5        | 20671        | 10-4865    | 07-01430   | ---   |
| HA-6        | LW-15957     | 10-5219    | 08-06394   | ---   |
| MA-3PA      | LW-16073     | 10-5220    | 08-06395   | ---   |
| MA-3PA      | ---          | 10-5220-E  | 07-01464   | ---   |
| HA-6        | LW-16066     | 10-5221    | 07-01465   | ---   |
| HA-6        | LW-15958     | 10-5224    | 08-06396   | ---   |
| MA-4SPA     | 77279        | 10-4910    | 08-06381   | ---   |

| Carb. Model | Lycoming P/N | Vendor P/N | Our P/N  | Price |
|-------------|--------------|------------|----------|-------|
| MA-4SPA     | LW-16559     | 10-4910-1  | 08-06382 | ---   |
| MA-3A       | 77585        | 10-4953    | 08-06383 | ---   |
| MA-6AA      | 77888        | 10-4975    | 07-01434 | ---   |
| MA-3PA      | 77939        | 10-4978-1  | 07-01435 | ---   |
| MA-4-5      | LW-10064     | 10-5034    | 08-06385 | ---   |
| MA-4-5      | LW-10196     | 10-5042    | 07-01438 | ---   |
| MA-3PA      | LW-10619     | 10-5050    | 08-06386 | ---   |
| MA-4-5      | LW-10540     | 10-5054    | 08-06387 | ---   |
| MA-3PA      | LW-13133     | 10-5126    | 08-06388 | ---   |
| HA-6        | LW-13757     | 10-5189    | 07-01447 | ---   |
| MA-4-5      | LW-15380     | 10-5193    | 08-06390 | ---   |
| HA-6        | LW-15504     | 10-5200    | 07-01450 | ---   |
| HA-6        | LW-15626     | 10-5206    | 07-01453 | ---   |
| HA-6        | LW-15674     | 10-5211    | 07-01460 | ---   |
| HA-6        | LW-15985     | 10-5211-1  | 07-01461 | ---   |
| MA-4-5      | 72740        | 10-4404    | 08-06375 | ---   |
| MA-4SPA     | 78728        | 10-5009    | 08-06384 | ---   |
| MA-4SPA     | 13659        | 10-5135    | 08-13873 | ---   |
| MA-3A       | 15496        | 10-5199    | 08-06391 | ---   |
| MA-4SPA     | 15986        | 10-5217    | 08-06392 | ---   |
| MA-3SAP     | 0-290-D      | 10-3346-1  | 07-00870 | ---   |
| \$600.00    | LW-16206     | 10-5227    | 07-01467 | ---   |
| \$699.00    | LW-15959     | 10-5230    | 08-06397 | ---   |
| HA-6        | LW-15960     | 10-5235    | 08-06398 | ---   |

\*\*\*NOTE\*\*\*

Customer will need to provide core for overhaul in the event our supplier does not have cores available to overhaul.

If you do not see your model # here please contact Aircraft Spruce Sales Department for pricing and availability .

\*All prices shown are with factory acceptable exchange carburetor.

Send exchange carburetor core to Aircraft Spruce. Upon factory approval of core, you will be refunded the core charge.

**BE CERTAIN ALL FUEL IS REMOVED FROM THE CORE.**

If Carburetor is not in stock we can have yours overhauled in 5-7 working days. Please call or email for more information.

## CONTINENTAL CARBURETORS

| Part No.   | Carb. Model | O.E.M. P/N | Our Part No. | Our Price |
|------------|-------------|------------|--------------|-----------|
| 10-3168    | MA-4-5      | 520120     | 07-01369     | ---       |
| 4895-T     | MA-3SPA     | 530490     | 08-06380     | ---       |
| 10-3649-1  | MA-4-5      | 535207     | 07-01370     | ---       |
| 10-3859-1  | MA-4-5      | 538872     | 08-06371     | ---       |
| 10-3965-12 | MA-4-5      | 539883     | 10-03965-12  | ---       |
| 10-4171    | MA-4-5      | 626789     | 07-01351     | ---       |
| 10-4191    | MA-4-5      | 626859     | 07-01375     | ---       |
| 10-4233    | MA-3SPA     | 627365     | 08-06374     | ---       |
| 10-4240    | MA-3SPA     | 627637     | 07-01377     | ---       |
| 10-4457    | MA-3SPA     | 629175     | 07-01378     | ---       |
| 10-4893-1  | MA-4-5      | 641139     | 08-06378     | ---       |
| 10-4894    | MA-3SPA     | 633028     | 08-06379     | ---       |
| 10-5067    | MA-3SPA     | -          | 07-01381     | ---       |
| 10-5082    | MA-3SPA     | 637035     | 07-01382     | ---       |
| 10-5128    | MA-3SPA     | 640416     | 07-01385     | ---       |
| 10-5192    | MA-3SPA     | 641860     | 07-01386     | ---       |
| 10-5284    | MA-4-5      | 646232     | 08-06404     | ---       |

\*All prices shown are with factory acceptable exchange carburetor. Add core charge on all models to each price shown. Send exchange carburetor core to Aircraft Spruce. Upon factory approval of core, you will be refunded the core charge.

**BE CERTAIN ALL FUEL IS REMOVED FROM THE CORE.**

FRANKLIN ENGINE CARBURETORS ALSO AVAILABLE. ADVISE EXACT ENGINE AND CARBURETORS ALSO AVAILABLE. ADVISE ENGINE AND CARBURETOR MODEL NUMBERS AND REQUEST QUOTATION