

CARBURETORS



Customer will need to provide core for overhaul in the event that our supplier does not have cores available to overhaul

REPLACEMENT CARBURETORS FROM MARVEL-SCHEBLER

Carburetor exchange program covers all popular Marvel Schebler/Facet general aviation carburetors. The carburetors are overhauled to the strictest industry standards and carry a full 6 month warranty (from date of installation). Most carburetors are available from stock or within a week and are furnished complete with gaskets.

Due to the various configurations of carburetor installations, we suggest you retain your carburetor core until receiving the exchange unit. This will enable you to transfer all external fittings and installation hardware to the new exchange unit. All cores being returned for credit shall be, as removed from the engine, complete and not disassembled. A reduction in core credit is charged for missing or damaged parts.

- Precision Carburetors
- TCM Fuel Systems
- Flow Dividers
- Fast Turn Time on Overhauls
- Unmatched Quality
- 100% calibration of fuel pumps and servos.
- Precision Fuel Servos
- Romec Fuel Pumps
- FAA/PMA Approved Replacement Parts
- Carburetor Overhaul Quick Kits
- Highly skilled/trained technicians

LYCOMING CARBURETORS

Carb. Model	Lycoming P/N	Vendor P/N	Our P/N	Price
MA-3A	61547	10-3103-1	10-03103-1	.
MA-4SPA	69250	10-3678-12	08-06325	.
MA-4SPA	72394	10-3678-32	08-06326	.
MA-4-5	71098	10-3878	08-06372	.
MA-4-5	71710	10-4164-1	08-06373	.
MA-4-5	66458	10-2827	07-01405	.
MA-4-5	66869	10-3323	07-01411	.
MA-3SPA	62830	10-3565-1	07-01413	.
MA-4-5	69540	10-3634	07-01415	.
MA-4-5	71546	10-3856-1	07-01417	.
MA-4-5	71685	10-3856-12	07-01418	.
MA-4-5AA	71684	10-4025-12	07-01421	.
MA-6AA	72407	10-4218-1	07-01424	.
MA-4-5	72386	10-4329	07-01426	.
MA-4-5	74121	10-4404-1	08-06376	.
MA-6AA	73899	10-4438-1	07-01428	.
MA-5	20671	10-4865	07-01430	.
HA-6	LW-15957	10-5219	08-06394	.
MA-3PA	LW-16073	10-5220	08-06395	.
MA-3PA	---	10-5220-E	07-01464	.
HA-6	LW-16066	10-5221	07-01465	.
HA-6	LW-15958	10-5224	08-06396	.
MA-4SPA	77279	10-4910	08-06381	.

Carb. Model	Lycoming P/N	Vendor P/N	Our P/N	Price
MA-4SPA	LW-16559	10-4910-1	08-06382	.
MA-3A	77585	10-4953	08-06383	.
MA-6AA	77888	10-4975	07-01434	.
MA-3PA	77939	10-4978-1	07-01435	.
MA-4-5	LW-10064	10-5034	08-06385	.
MA-4-5	LW-10196	10-5042	07-01438	.
MA-3PA	LW-10619	10-5050	08-06386	.
MA-4-5	LW-10540	10-5054	08-06387	.
MA-3PA	LW-13133	10-5126	08-06388	.
HA-6	LW-13757	10-5189	07-01447	.
MA-4-5	LW-15380	10-5193	08-06390	.
HA-6	LW-15504	10-5200	07-01450	.
HA-6	LW-15626	10-5206	07-01453	.
HA-6	LW-15674	10-5211	07-01460	.
HA-6	LW-15985	10-5211-1	07-01461	.
MA-4-5	72740	10-4404	08-06375	.
MA-4SPA	78728	10-5009	08-06384	.
MA-4SPA	13659	10-5135	08-13873	.
MA-3A	15496	10-5199	08-06391	.
MA-4SPA	15986	10-5217	08-06392	.
MA-3SAP	0-290-D	10-3346-1	07-00870	.
\$600.00	LW-16206	10-5227	07-01467	.
\$699.00	LW-15959	10-5230	08-06397	.
HA-6	LW-15960	10-5235	08-06398	.

NOTE

Customer will need to provide core for overhaul in the event our supplier does not have cores available to overhaul.

If you do not see your model # here please contact Aircraft Spruce Sales Department for pricing and availability .

*All prices shown are with factory acceptable exchange carburetor.

Send exchange carburetor core to Aircraft Spruce. Upon factory approval of core, you will be refunded the core charge.

BE CERTAIN ALL FUEL IS REMOVED FROM THE CORE.

If Carburetor is not in stock we can have yours overhauled in 5-7 working days. Please call or email for more information.

CONTINENTAL CARBURETORS

Part No.	Carb. Model	O.E.M. P/N	Our Part No.	Our Price
10-3168	MA-4-5	520120	07-01369	.
4895-T	MA-3SPA	530490	08-06380	.
10-3859-1	MA-4-5	538872	08-06371	.
10-3965-12	MA-4-5	539883	10-03965-12	.
10-4171	MA-4-5	626789	07-01351	.
10-4191	MA-4-5	626859	07-01375	.
10-4233	MA-3SPA	627365	08-06374	.
10-4240	MA-3SPA	627637	07-01377	.
10-4457	MA-3SPA	629175	07-01378	.
10-4893-1	MA-4-5	641139	08-06378	.
10-4894	MA-3SPA	633028	08-06379	.
10-5067	MA-3SPA	-	07-01381	.
10-5082	MA-3SPA	637035	07-01382	.
10-5128	MA-3SPA	640416	07-01385	.
10-5192	MA-3SPA	641860	07-01386	.
10-5284	MA-4-5	646232	08-06404	.

*All prices shown are with factory acceptable exchange carburetor. Add core charge on all models to each price shown. Send exchange carburetor core to Aircraft Spruce. Upon factory approval of core, you will be refunded the core charge.

BE CERTAIN ALL FUEL IS REMOVED FROM THE CORE.

FRANKLIN ENGINE CARBURETORS ALSO AVAILABLE. ADVISE EXACT ENGINE AND CARBURETORS ALSO AVAILABLE. ADVISE ENGINE AND CARBURETOR MODEL NUMBERS AND REQUEST QUOTATION